
8-32 x 1/2
BUTTON HEAD
SCREW, 3 PLACES
8090P
PLATFORM
AS-1.50
4 PLACES
(DIFFERENT AS SPACERS CAN
BE USED OR ADDED TO ACHIEVE
DIFFERENT HEIGHTS)
1/4-20 x 1/2
CAP SCREW, 8 PLACES
(SCREW LENGTH WILL
BE DETERMINED BY
THE AS SPACERS
USED)
1/4-20 SET SCREW
USED FOR MOUNTING
THREADED AS SPACER
TO 1280P PLATFORM,
4 PLACES
AS-2.00
4 PLACES
(DIFFERENT AS SPACERS CAN
BE USED OR ADDED TO ACHIEVE
DIFFERENT HEIGHTS)
AS-2.00 SPACER
WITH 1/4-20
THREADED HOLE
AS-1.50 SPACER
WITH 1/4-20
THREADED HOLE
AS-1.00 SPACER
WITH THROUGH HOLE
AS-.500 SPACER
WITH THROUGH HOLE
AS-.250 SPACER
WITH THROUGH HOLE
AS-.125 SPACER
WITH THROUGH HOLE
1280P PLATFORM
2 PLACES
PSR-6
4 PLACES
1/4-20 x 2
CAP SCREW
1/4-20 SET SCREW
USED FOR MOUNTING
PSR-6 TO THREADED
AS SPACER, 4 PLACES
1/4-20 x 1
CAP SCREW
1/4-20 x 3/4
SET SCREW
1/4-20 x 1 1/2
CAP SCREW
1/4-20 SET SCREW
USED FOR MOUNTING
PSR-6 TO ISOLATION
TABLE, 4 PLACES
1/4-20 x 1/2
CAP SCREW
WASHER
11.00 x 22.00
siskiyou
Website: www.siskiyou.com
Toll-Free 877-313-6418